

Images of the Bonnington-Coventry corridor



Image 1 (left):
Hydro, Tel, Cable infrastructure
at top (Bonnington Dr.) end of
park land corridor.

Image 2 (below):
Approximate 2m grade change
(existing vegetation) that would
require bank retention and stairs.
Adjacent bank retention by
neighbours visible.





Image 3 (above): Facing west (towards Bonnington Dr.) RDN sewer infrastructure visible. Bedrock and grade change visible behind yellow pipe. Stair work in this area would require monitoring next to existing boulder retaining wall.

Image 4 (below): Facing east (towards Coventry Pl.) MOTI stormwater manhole visible. Stair landing placement would need to be setback from infrastructure.





Image 5 (above): Small group of regenerating evergreen trees. One or two small diameter trees would require removal to open up walkway. Compatibility with underground infrastructure to be confirmed.