

Slope to Foreshore Rating: 1 = nearly level 2 = moderate slope 3 = steep 4 = cliff

Those ranked '1' visited by POSAC on November 24 and 28, 2017

Inventory List of Beach Accesses Area E										
ROW Number	Reviewers	Date	Development Suitability	Development Comments	Current State	Human Changes/Structures	Slope To Foreshore	Foreshore Type	Other	Historical/FN Interests
E04	DM/MC	Sept. 7 2017	1	in conjunction with Rowland Park E29	Gravel Road to beach. Park and ROW treed	gravel road	1	Gravel beach. Extensive walking length on beach.		U
E23	DM/MC	1-Jun-17	1		Grass/brush/tiny drainage course		1	gravel/pebble beach	Warm and sheltered	
E24	DM/MC	1-Jun-17	1		Brush, trees, some invasives	Minor trail	2	Rocky; pocket gravel beach	Neighbours have cliffs; would support development	
E29	DM/MC	Sept 12 2017	1	1 to 2	Treed, dense under-brush. Gravel road part way in. Deer path. By Moorecroft.		2	Gravel to rock and small boulder, driftwood at shore.	Connects around the bay to Oakleaf @ lower tide. Possibly to Moorecroft as well.	No known
E32	DM/MC/WS	22-May-17	1		Trees/brush at cliff	trail	1	cobbles/lots of driftwood	Walk on beach; easy to develop; some parking options	
E33	DM/MC/VS	22-May-17	1		Trees/brush; rough		2 - 4@foreshore	Rocky; uneven	Viewpoint potential	
E43	DM/MC	26-May-17	1		Road half way; Periwinkle	Neighbour has barricaded part of ROW for private fire pit and chairs	2	Rock/boulders; driftlogs;	Locals intersted in development of ROWs so seniors could see whales swim by	
E53	DM/MC	1-Jun-17	1		Trees; rough ground	none	1 - 2 - 1@foreshore	Rocky	Wide ROW; Driveway for 1675 Claudet may encroach; would need a trail created	
E56	DM/MC	Sept 5 2017	1	Good Parking	Trees, bush	Well used trail	2	Sandstone and rock and boulders. Access to a lot of foreshore.		
E57	DM/MC	Sept 5 2017	1		Treed	Good Trail	1	Gravel beach contiguous (c with line on top) E58		
E65	DM/MC	Sept 8 2017	1		Natural brush, trees	Minor Trail	1	Sand/gravel. Mudflats below. Extensive LT zone	In WMA	U
E66	DM/MC	Sept 8 2017	1	Enhance E65 or E66 Same beach, similar habitat	Trees, brush	Good well used path to beach	1	Gravel to intertidal grass and algae		No Known

Development Suitability Ranking: 1 = very suitable 2 = suitable with constraints (e.g. stairs) 3 = significant modifications required 4 = not suitable (e.g. cliff) 5 = already developed/partially developed

Inventory List Organized by Development Suitability Ranking

2

Slope to Foreshore Rating: 1 = nearly level 2 = moderate slope 3 = steep 4 = cliff

Those ranked '1' visited by POSAC on November 24 and 28, 2017

ROW Number	Reviewers	Date	Development Suitability	Development Comments	Current State	Human Changes/Structures	Slope To Foreshore	Foreshore Type	Other	Historical/FN Interests
E03	DM/MC	Sept. 7 2017	2	can access beach from Rowland	Trees, Brush, swampy.	Minor bushwacking trails	2	Gravel to sand. Grassy bench @HTL	Blokker Road	n/a
E06	DM/MC	Sept. 7 2017	2	Still need access development at bottom of slope to stairs.	Roadend - recent gravel added to slope		3	Large gravel and stones		No known
E12	DM/MC	Sept. 7 2017	2	Minimal parking, beach unusable, great outlook, lots of good sitting rock.	Trees, brush, some daphne	Good trail	2 to 4 at waters edge	Rocky with drop off		
E21	DM/MC	1-Jun-17	2		Trees/cleared	Minor Trails/local use	3	Rocky	Would need stairs - limited parking	
E26	DM/MC	1-Jun-17	2			Neighbours encroached on ROW and it is difficult to locate	2 - 3@foreshore	Pebble beach	Would need stairs	
E38	DM/MC	26-May-17	2		Cleared; invasives (daphne, stinging nettle)	trail	2	Boulders, rocks, oyster bed	Limited parking as Ludgate Rd. narrow	
E42	DM/MC	26-May-17	2		Unkempt grass; blackberries	Previously cleared but not maintained	1 - 3@foreshore	Rocky Shelf; tiny pocket beach in Intertidal	Nice views	
E47	DM/MC	26-May-17	2		Mostly cleared	Ditto	1 - 2 - 4@foreshore	Rocky beach	Outstanding view; would need fence at top of cliff Neighbour supports usage	
E49	DM/MC	26-May-17	2		Steep slope w/Garry oak above foreshore	1/2 is Whitecap Rd; neighbour barriers to discourage access	1 - 3@foreshore		Views compromised by tree location	
E58 (Wall Beach)	DM/MC	Sept 5 2017	2	Off street parking limited	Road end, vehicle accessible	Lrg.	1	sand, gravel to mud @low tide		
E64	DM/MC	Sept 6 2017	2	Could develop switchback trail	Trees, brush, moss	Lightly used trail, rough switchback trail down embankment	1 to 4	Mud, large rocks, boulders, wide intertidal		
E07	DM/MC	Sept. 7 2017	3	switchback trail and stairwell required to access beach. *Teds Road-easy access to same beach	Natural, treed	None. Not even a trail	Three to four	Wide flat gravel beach on lower tide		Unknown

Development Suitability Ranking: 1 = very suitable 2 = suitable with constraints (e.g. stairs) 3 = significant modifications required 4 = not suitable (e.g. cliff) 5 = already developed/partially developed

October 22, 2017

Inventory List Organized by Development Suitability Ranking

3

Slope to Foreshore Rating: 1 = nearly level 2 = moderate slope 3 = steep 4 = cliff

Those ranked '1' visited by POSAC on November 24 and 28, 2017

ROW Number	Reviewers	Date	Development Suitability	Development Comments	Current State	Human Changes/Structures	Slope To Foreshore	Foreshore Type	Other	Historical/FN Interests
E13	DM/MC	Sept 7 2017	3	3 to 4 Poor parking - 3 max at roadsid, Would require steep stairs	Tree: Willow, thistle and blackberry		4	Rock and some gravel and cobble		
E14	DM/MC	Sept 7 2017	3	probably stairs	Trees, brush, arbutus, oak, fir		3 to 4	Gravel , cobble, rocks		
E15	DM/MC	Sept 7 2017	3	could be a viewpoint with benches or picnic table. Good outlook to islands	Road end - Garry Oak, Fir, Grasses	None	2 to 4	Rocky, boulder, sandstone		
E22	DM/MC	1-Jun-17	3		Trees	Minor encroachment by neighbours	3	Nice pebbly beach	Would need stairs all the way	
E25	DM/MC	1-Jun-17	3		Trees, brush, swamp, creek	Neighbour's stairwell and fence probably in ROW	1 - 3@ foreshore	Pebble beach	Would require drainage, trails, stairs	
E40	DM/MC	26-May-17	3		Trees, brush, grass, some native Camas and Rose	Encroachment - yard debris and discarded junk	2	Rocky; uneven; no beach		
E41	DM/MC	26-May-17	3		Road to brush trail with Daphne	Road partway	4	Rocks/boulders	Need stairs to access foreshore; good viewpoint	
E51	DM/MC	1-Jun-17	3		Trees; some broom/daphne	No trail but stairs at cliff	2 - 4@foreshore	Rocky; some pebble beach @ high tide	Would require stairs and fences	
E55	DM/MC	Sept 6 2017	3		Trees, brush, wetland	None	1	Strewn boulder and rock over sandstone. Wide walkable beach access to Northwest Bay		
E02	DM/MC	Sept. 7 2017	4		Natural High Estuary	Minor Trails	1	Mud and Intertidal Vegetation	Adjacent wildlife preserve- National Wildlife Area (WMA)	
E08	DM/MC	Sept. 7 2017	4	Midden?- oyster shell beach	Treed, daphne	Trail-post public access	3	Upheaval Rock		First Nations bi-valve tenure
E10	DM/MC	Sept. 7 2017	4	Used as an alternative entrance to brickyard bay	Trees	Well used trail to Brickyard	3 - Bolders, rough terrain			
E11	DM/MC	Sept. 7 2017	4		Rip rap, pear tress, power boxes @ road.	Utility Corridor	2 to 3	Rocky		

Development Suitability Ranking: 1 = very suitable 2 = suitable with constraints (e.g. stairs) 3 = significant modifications required 4 = not suitable (e.g. cliff) 5 = already developed/partially developed

Inventory List Organized by Development Suitability Ranking

4

Slope to Foreshore Rating: 1 = nearly level 2 = moderate slope 3 = steep 4 = cliff

Those ranked '1' visited by POSAC on November 24 and 28, 2017

ROW Number	Reviewers	Date	Development Suitability	Development Comments	Current State	Human Changes/Structures	Slope To Foreshore	Foreshore Type	Other	Historical/FN Interests
E16	DM/MC	Sept 7 2017	4		Roadfill Schooner Cove and nonnative grasses		2	Rocky - Rip Rap		
E17	DM/MC	1-Jun-17	4		Treed		4	Rocky Beach	By Schooner Cove Marina	
E17	DM/MC	June 1 2017	4		Treed		4 - Steep cliff from road	Rocky Beach	By Schooner Cove Marina	
E19	DM/MC	1-Jun-17	4		Mowed	Mowed	1 - 4@foreshore	Rocky	Nice View but Cliff would be challenging to Access	
E28	DM/MC	1-Jun-17	4		Trees/brush at cliff	Paved access; hedges	4	Rocky	Cliff	
E39	DM/MC	26-May-17	4		cleared; lawn	developed road access	2	rough lava rocks	no parking options; narrow	old asphalt/concrete/pilings in foreshore
E48	DM/MC	26-May	4			Complete encroachment by neighbours on both sides			Driveway; retaining wall; etc.	
E52	DM/MC	1-Jun-17	4		Trees/brush	charis; stairs; no trail	1 - 4@foreshore	gravel; cobble rock	View compromised by oak/fir	
E59	DM/MC	Sept 5 2017	4		Treed, blackberry, ivy	Short trail through blackberry to cliff	1 to 4	Sandy, gravel beach		
E01	DM/MC	Sept. 7 2017	5		Cleared	Road Access to Beach	1	Gravel to Mud Flats. Extensive low tide area.		Yes, Bivalve Tenure
E09	DM/MC	Sept. 7 2017	5		Established Park with Trail and stairs to gravel beach	Established Park with Trail and stairs to gravel beach	n/a	n/a	E09 = Ainsley Place Community Park	
E18	DM/MC	1-Jun-17	5		Cleared	Trail	1	Rocky Beach		
E20	DM/MC	1-Jun-17	5						E20 = Blueback Community Park	
E27	DM/MC	1-Jun-17	5						E27 = Park Place Community Park	
E31	DM/MC/VS	22-May-17	5	Trail to be contained to ROW. Leads into Moorecroft. Not suitable to continue as beach access.	treed with informal trail that weaves in and out of ROW		3 to 4	Rock Shelves, adjacent to sensitive habitat/in MRP.	Could formalize as northern trail access to Moorecroft Regional Park	

Development Suitability Ranking: 1 = very suitable 2 = suitable with constraints (e.g. stairs) 3 = significant modifications required 4 = not suitable (e.g. cliff) 5 = already developed/partially developed

October 22, 2017

Inventory List Organized by Development Suitability Ranking

5

Slope to Foreshore Rating: 1 = nearly level 2 = moderate slope 3 = steep 4 = cliff

Those ranked '1' visited by POSAC on November 24 and 28, 2017

ROW Number	Reviewers	Date	Development Suitability	Development Comments	Current State	Human Changes/Structures	Slope To Foreshore	Foreshore Type	Other	Historical/FN Interests
E34	DM/MC/VS	22-May-17	5		Cleared	gravel trail; bench	1	gravel beach	local kayaks stored there. Drainage channels	
E35	DM/MC/VS	22-May-17	5		Cleared	Old stairs and fence	1 - 3@foreshore	pebble beach		
E36	DM/MC/VS	22-May-17	5		Cleared	trail; a few logs lashed together for	1	Rocky; some pebbles		
E37	DM/MC/VS	22-May-17	5		Cleared		1	Rocks	boats, kayaks, paddle boards st shore	old public access marker at beach
E44	DM/MC	26-May-17	5		Road to steep stairs down to rock shelves		1 - 3@foreshore	Rock Shelves	Concrete stairs	
E46	DM/MC	26-May-17	5		Treed	trail			Provides alternative access to Beachcomber Park	
E50	DM/MC/VS	22-May-17	5		cleared	trail; fenced one side	1	pebbles; driftwood	Lovely small cove; heavily used. The Jib is	
E54	DM/MC	1-Jun-17	5		Treed; creek ends in gravel beach berm	Trail	1	Pebble beach	Could use more parking	
E60	DM/MC	Sept 5 2017	5		Treed, bush blackberry, daphne, ivy	Well used trail	1 to 3	Deep sandstone beach-full lot wide @ water		
E61	DM/MC	Sept 6 2017	5	Good Parking	Tree, brush, blackberry, ivy, invasive daphne	Trail - well used	2	Sandstone beach		No known
E62	DM/MC	Sept 6 2017	5	six or eight parking spaces offroad	Treed, bush	Trail to beach	1	Pocket gravel beach with sandstone either side		No Known
E63	DJ/MC	Sept 6 2017	5		Treed with paths, invasive ivy	Trails, park bench on concrete slab	1	Sandstone beach	end of cul de sac with only 2 parking spots, therefore, parking a chronic issue with neighbours.	None

Development Suitability Ranking: 1 = very suitable 2 = suitable with constraints (e.g. stairs) 3 = significant modifications required 4 = not suitable (e.g. cliff) 5 = already developed/partially developed

October 22, 2017